



<b>Project Title:</b>	Canterbury Signal Box
<b>Client:</b>	Network Rail - Kent
<b>Date of Work:</b>	October 2011

Project Description

The scheme requirement was to refurbish a timber signal box and the supporting steel gantry structure of riveted construction.

A small amount of asbestos removal was required under the terms of the contract. These were undertaken by a specialist contractor.

The signal box is a grade 2 listed structure, and as such all repairs were undertaken on a like for like basis.

Project Constraints

Public Interface

Work at Height

Asbestos removal

Lead in paint (Operatives supplied with appropriate safety apparatus and blood tests taken before and on completion of works).

Limited painting time due to winter weather