

Project description	Project Constraints Public Interface
Re-lining of existing subway with aluminium cladding system class b fire rating,	Keeping subway operational
and lighting system within lower subway.	Pedestrian Management
Both staircase walls were rendered over defective brickwork and new DDA compliance handrail systems and stair treads installed.	