

Project Description	<u>Project Constraints</u> Traffic Management.
<u>South voussoir</u> Deeply spalled brickwork in the following areas were cut out and repaired: 1 st ring: 9no, 2 nd ring: 6no, 3 rd ring: 8no, 4 th ring: 16no.	Work at high level. Poor condition of structure. Sourcing bricks of matching size/colour.
<u>North voussoir</u> Deeply spalled brickwork in the following areas were cut out and repaired: 1 st ring: 29no, 2 nd ring: 48no, 3 rd ring: 47no, 4 th ring: 53no.	Public Interface. 3 rd party negotiations (landowners).
Soffit 7m ² of deeply spalled brickwork in the arch soffit were cut out using a temporary centring system supports.	Access constraints. Expertise required for the installation of the proprietary propping system.
<u>Fly tip removal</u> 14no discarded tyres beneath the bridge deck were removed from site and disposed off at a licensed disposal point.	Expertise required to replace overhead brickwork.